

Inspection Photos
Operator: Hilcorp Energy
API: 067-09369
Date: 7/28/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of erosional channeling occurring at the well pad entrance where stormwater flows down the access road into culvert outlet (Photo 3).



Photo 3. View of the culvert outlet at the well pad entrance. Culvert is full of sediment and needs maintenance.



Photo 4. View of area along the well pad diversion, where diversion berm is damaged by truck tracks and erosion, and sediment is discharging onto the well pad resulting in deep rutting.



Photo 5. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing within the interim reclamation areas with rubber rabbitbrush, crested wheatgrass, and western wheatgrass.



Photo 6. View of reference area vegetation comprised of pinyon and juniper woodland, with black sage, blue grama, and *Tetrandeum* sp.