

FORM
INSPRev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/04/2020

Submitted Date:

08/05/2020

Document Number:

690101994

FIELD INSPECTION FORM

Loc ID 319353 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		NBL_DJBU_Inspections@NBLENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243322	WELL	PR	04/19/2010	OW	123-11113	RUFF 1	EG

General Comment:

Engineering Integrity Inspection; Flowline Inspection
Photos Uploaded

Inspected FacilitiesFacility ID: 243322 Type: WELL API Number: 123-11113 Status: PR Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines
<u>Flowline Description</u>		
Flowline Type: <u>Non-Well Site</u>	Size:	Material:
Variance:	Age:	Contents:
<u>Integrity Summary</u>		
Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:
<u>Pressure Testing</u>		
Witnessed:	Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>		
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment		
<u>Comment:</u>	Well (Ruff 1) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402349083 was received on 03/23/2020. COGCC form 42 Flowline Pre Abandonment - 30-day notice Doc was updated to 7/28/2020. COGCC form 44 (off location flowline abandonment) notice Doc #402430095 was received on 06/24/2020. No flowline risers exist a PA well location. Flowline riser at inlet to heated horizontal separator has been disconnected and OOSLAT; however off location flowline abandonment/ removal has not been completed and remains in progress. The shared facility/ battery services 5 wells total; all flowlines SI/ OOSLAT at remaining wellheads and surface equipment.	
<u>Corrective Action:</u>		<u>Date:</u>

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101995	Signage at battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5217517
690101996	Flowline isolated at inlet to separator (OOSLAT)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5217518
690101997	View from PA well to facility/ battery (to North)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5217519