

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2020

Submitted Date:

07/30/2020

Document Number:

699700178

FIELD INSPECTION FORM

 Loc ID 316204 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10539
 Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
 Address: 1125 ESCALANTE DR
 City: RANGELY State: CO Zip: 81648
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Moran, Rick		rick.moran@state.co.us	
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	All inspections
Bleil, Rob	970-290-2912	rbleil@utahgascorp.com	
Hale, Steven	(970) 290-2912	shale@utahgascorp.com	Environmental Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256439	WELL	PR	04/25/2000	GW	103-10000	PARK MOUNTAIN FEDERAL 9026	EI

General Comment:

On July 20, 2020, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of UTAH GAS OP LTD DBA UTAH GAS CORP (Utah Gas operator #10539) PARK MOUNTAIN#9026 Location ID 316204.

This is a follow up of COGCC Field Inspector Rick Moran Inspection Doc #700402442.

Audible leak present at wellhead. COGCC contacted Utah Gas personnel Steven Hale via cellphone on 7/20/2020 with regards to the audible leak. 7/21/2020 Steven Hale contacted COGCC John Heil to report that the leaking wellhead had been repaired by field personnel.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Tanks and tank lids and other debris associated with the tank battery.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/30/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 256439 Type: WELL API Number: 103-10000 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: 7/16/2020 a fire was discovered at the location after thunderstorms producing lightning were present in the area the previous day. Lightning struck the tank battery causing the tanks to lose their lids and ignite (Inspection Doc #700402442). 7/20/2020 two tanks in disrepair were observed inside an earthen, secondary containment structure. There were no apparent impacts from the tanks within the earthen secondary containment structure or on the well pad at time of inspection.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402456852	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214177
699700180	20200720 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214176