

**Inspection Photos**  
**Operator: Benson Montin Greer**  
**API: 067-06159**  
**Date: 7/28/2020**



Photo 1. View of the northeastern edge facing center. Plugged well marker



Photo 2. View of exposed pipe and wiring on the well pad, needing to be removed.



Photo 3. View of the western project area, cut-slope is not contoured or stabilized, as sediment deposition observed at the toe of the slope.



Photo 4. View of bare area in the southeastern project area, needing reclamation.



Photo 5. View of reference area vegetation comprised of pinyon and juniper woodland, with black sage, blue grama, and *Tetaneuris* sp.