

Inspection Photos
Operator: BP America
API: 067-08689
Date: 8/3/2020



Photo 1. View of the project area from the nottheastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with crested wheatgrass.



Photo 3. View of wattles that are no longer functioning within the eastern project area.



Photo 4. View of reference area vegetation comprised of pinyon juniper woodland with sagebrush and blue grama in the understory.