

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2020

Submitted Date:

08/07/2020

Document Number:

690006301

FIELD INSPECTION FORM

Loc ID 420219 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420235	WELL	SI	12/01/2019	GW	123-32515	DECHANT STATE H36-11	PA
420315	WELL	PA	08/29/2018	OW	123-32543	DECHANT STATE H36-21D	PA

General Comment:

Location

Overall Good:

Signs/Marker:

Type			
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#			corrective date
Type: Emission Control Device	# 0			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 0			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 0			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 0			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment:						
Corrective Action:				Date:		

Paint

Condition	<input style="width: 150px;" type="text"/>
Other (Content)	<input style="width: 800px;" type="text"/>
Other (Capacity)	<input style="width: 800px;" type="text"/>
Other (Type)	<input style="width: 800px;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment:					
Corrective Action:				Date:	
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 420235 Type: WELL API Number: 123-32515 Status: SI Insp. Status: PA

Facility ID: 420315 Type: WELL API Number: 123-32543 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
Wells have been plugged. Former battery location: 420221 in the process of being removed. At time of inspection GMR and pig station remains.	carlilec	08/07/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690006302	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5219356