

Inspection Photos

8/04/2020

Operator: NONSUCH NATURAL GAS INC #
10163

Location ID: 324169
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 1: Photo taken from the access road north of the Location, facing south.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 2: Photo of sediment trap on the north end of the Location.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 3: Photo of sediment trap on the north end of the Location.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 4: Photo taken from the northwest end of the location, facing south. Photo of interim areas. Photo shows interim areas is predominantly bare. Vegetation establishment is mostly noxious weeds such as Hounds tongue and Bull thistle. Some evidence of recent weed spraying evident, however weed management appears insufficient as many weeds appear to remain viable.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 5: : Photo taken from the northwest end of the location, facing south. Photo of interim areas. Photo shows interim areas is predominantly bare. Reclamation is not progressing towards 1003 standards.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 6: Photo shows soil surface of interim areas. Soils appear to be subsoils; it does not appear that the topsoil horizon has been returned to their original relative position. Reclamation is not progressing towards 1003 standards.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 7: Photo taken from the western interim areas, facing south. Photo shows interim areas are not progressing towards 1003 standards.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 8: Photo taken from the western interim areas, facing south. Photo of production area. Photo also shows interim areas are not progressing towards 1003 standards.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 9: Photo taken from the wester interim areas. Photo shows BMPs missing or insufficient to stabilize soils on slope. Photo also shows interim areas are not progressing towards 1003 standards.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 10: Photo taken the interim areas on the south end of the Location, facing southwest. Photo shows BMPs missing or insufficient to stabilize soils on slope. Photo also shows interim areas are not progressing towards 1003 standards, and noxious weeds.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 11: Photo taken the interim areas on the south end of the Location, facing southwest. Photo shows BMPs missing or insufficient to stabilize soils on slope. Photo also shows interim areas are not progressing towards 1003 standards.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 12: Photo taken the interim areas on the west end of the Location, facing west. Photo shows BMPs missing or insufficient to stabilize soils on slope. Photo also shows interim areas are not progressing towards 1003 standards.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 13: Photo shows noxious weeds (Hounds tongue) on the interim areas.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 14: Photo taken from the north end of the Pad. Photo of Bull thistle on Location.