

Inspection Photos

8/04/2020

Operator: NONSUCH NATURAL GAS INC -
10163

Location ID: 324172
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172



Photo 1: Photo taken from the south end of the Location, facing north. Photo 1-2 provides an overview of the Location. Photo also shows noxious weeds on Location.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC - 10163
Location ID: 324172



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC - 10163
Location ID: 324172



Photo 3: Photo taken from the south end of the Location. Photo shows noxious weeds (Musk thistle, Houndstongue) on the Location.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC - 10163
Location ID: 324172



Photo 4: Photo taken from the south end of the Location, facing south. Photo shows noxious weeds (Musk thistle, hounds tongue) on the Location.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172



Photo 5: Photo of Musk thistle on the south end of the Location. Though evidence of senescence likely related to chemical herbicide was observed, weed management appears insufficient as large numbers of weeds observed on Location and access road remain viable.



Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC - 10163
Location ID: 324172



Photo 6: Photo taken from the southwest end of the location, facing northeast. Photo shows noxious weeds (dark vegetation) on interim and production areas.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172



Photo 7: Continued from photo 6.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172



Photo 8: Photo taken from the north end of the Location, facing south. Photo shows northern interim areas of the Location; Interim reclamation appears to be progressing towards 1003 standards.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172



Photo 9: Photo taken from the north end of the Location, facing northeast. Photo shows northern interim areas of the Location; Interim reclamation appears to be progressing towards 1003 standards.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172



Photo 10: Photo taken from the east end of the Location. Photo shows noxious weeds (Houndstongue rosettes) on the interim areas.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172



Photo 11: Photo of Musk thistle on the access road. Though evidence of senescence likely related to chemical herbicide was observed, weed management appears insufficient as large numbers of weeds observed on Location and access road remain viable.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172



Photo 12: Photo of Musk thistle and Houndstogoe on the access road. See comments under photo 11.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC - 10163
Location ID: 324172



Photo 13: Photo of Musk thistle and Houndstogoe on the access road. See comments under photo 11.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC - 10163
Location ID: 324172



Photo 14: Photo of well.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172



Photo 15: Photo of pit.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 324172




Photo 16: Photo of pit.

