

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 243662 Type: WELL API Number: 123-11454 Status: PA Insp. Status: WK

Workover

Comment: Wellbore has been cleaned to a depth of 385' KB, lay down drill collars and drill assembly, PU and RIH with 9 5/8" packer and set @ 380' KB for surface csg pressure test, pumped 43 bbls of fresh water down annulus and had returns external of surface csg, reset packer at various depths to determine hole depth, hole in surface csg was determined to be approximately 5' below surface grade.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697001797	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5219614