

Inspection Photos  
Operator: BP America  
API: 067-08204  
Date: 8/5/2020



Photo 1. View of the project area from the southeastern corner facing center.





Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, rubber rabbitbrush, and other grasses in a grazed condition.





Photo 3. View of erosional headcut (approximately 3-4 ft wide and 2-3 feet deep) forming in the northeastern project area where diversion from the northern project area meets a swale flowing from the north.





**Sign next to fired equipment with shotgun holes, that appears to be in use as a target.**



**Shotgun shells**

Photos 4-6. View of shotgun shells and sign next to submerged tank with evidence of shotgun holes.



Photo 7. View of reference area mixed pinyon and juniper woodland, sagebrush, with grasses and forbs largely in a grazed condition.