

Inspection Photos
Operator: BP America
API: 067-09060
Date: 8/5/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, and crested wheatgrass.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of Scotch thistles within the project area that appear to be herbicide-treated (approx. 500 individuals observed). Herbicide cover appears effective; however, additional treatment will be needed due to the extent of the infestation and late flowering condition of the individuals when treated.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of black sage, blue grama, gambel oak, snakeweed, and yellow rabbitbrush.