

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2020

Submitted Date:

08/10/2020

Document Number:

700402812

FIELD INSPECTION FORM

Loc ID 398240 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 24120
 Name of Operator: DIAMOND BACK DRILLING & SUPPLY INC
 Address: P O BOX 2622
 City: GRAND JUNCTION State: CO Zip: 81502

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Conklin, Curtis		curtis.conklin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231382	WELL	PA	02/29/1984	DA	103-09052	EMERALD 268	PA

General Comment:

A follow up inspection of FIR document 500157599 dated 4-7-1998.
 The following compliance issues are uncompleted:
 1) Reclamation not completed. Drilling cable on location of abandon well.
 This is a summary of inspection report 700402812.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type TRASH

Comment: Drilling cable.

Corrective Action:

Date:

Overall Good:

Spills:

Type Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 231382 Type: WELL API Number: 103-09052 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: PA between 1983 and 1985. The inspector did not probe into the mud filled 7" casing to determine if cement was present further down.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700402813	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5220131