



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	mechanical issue with valve on separator and tank see pic 6,10		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	09/10/2020
Type	WEEDS		
Comment:	weeds growing throughout location see pic 1,2,3,5,7,8,9		
Corrective Action:	Comply with Rule 603.f .	Date:	10/19/2019
Type	OTHER		
Comment:	Stained soil below valve on tank and separator see pic 6,10		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/19/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Type: Gas Meter Run	# 1			
Comment:	unable to inspect gas meter run due to spider web near box.			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	electric motor			
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Electric			
Corrective Action:				Date:
Type: Horizontal Heated Separator	#			

Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with oil tank				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:	Placard on one oil tank may need to be replaced soon				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
------	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 202953 Type: WELL API Number: 001-08358 Status: PR Insp. Status: PR

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On 8/10/2020 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at:  Well Name- Guthrie 2  Company Name- KPK  API- 05-001-08358  In Adams County Colorado.  While there, I observed producing well.  This is a follow up inspection from document #689501002 Corrective Actions are Delinquent.  During this inspection the following possible compliance issues were observed:  Stained soil below valve on tank and separator see pic 6,10  Properly treat or dispose of oily waste in accordance with 907.e. 10/19/19  Weeds growing throughout location see pic 1,2,3,5,7,8,9  Comply with Rule 603.f .10/19/19  Mechanical issue with valve on separator and tank see pic 6,10  Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 9/10/20  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  At time of inspection weather conditions were sunny and calm.  This is a summary of inspection report.</p>	medinaj	08/11/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501634	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221241">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221241</a>