

Inspection Photos

8/04/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335844

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 1: Photo of sign at location entrance

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 2: Photo taken from the east end of the production area, facing south. Photos 2-5 provide an overview of the Location from south, southwest, northwest to north.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 3: See comments under photo 2.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



20200804

Photo 4: See comments under photo 2.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 5: See comments under photo 2.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 6: Photo taken from the southwest end of the Location, facing east. Photo shows unmarked anchor.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 7: Continued from photo 6. Photo shows unmarked anchor location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 8: Photo taken from the southeastern areas of the location . Photo shows unmarked anchor.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 9: Photo taken from the western interim areas. Revegetation in these areas appears to be progressing towards 1000 series standards.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 10: Photo taken from the southwestern end of the storage are of the location, facing southwest. Photo shows erosion degradation.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 11: Photo taken from the west end of the Locaiton, facing east. Photo shows erosion degradation and sediment transport.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 12: Photo taken from the western interim areas of the Location. Photo shows bull thistle establishing on location. This is a Colorado State listed noxious weed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 13: Photo taken from the eastern interim areas of the Location, facing north. Photo shows BMPs missing or insufficient to stabilize slopes and/or prevent sediment transport

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 14: Photo taken from the eastern interim areas of the Location, facing southeast. Photo shows BMPs missing or insufficient to stabilize slopes and/or prevent sediment transport

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 15: Photo taken from the eastern interim areas of the Location, facing east. Photo shows BMPs missing or insufficient to stabilize slopes and/or prevent sediment transport

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 16: Photo taken from the eastern interim areas of the Location, facing east. Photo shows BMPs missing or insufficient to stabilize slopes and/or prevent sediment transport

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 17: Aerial photo taken east of the Location, facing west. Photo shows overview of the Location and fill slopes; BMPs missing or insufficient to stabilize slopes and/or prevent sediment transport

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 18: Aerial photo taken east of the Location, facing north. Photo shows overview of the Location and fill slopes; BMPs missing or insufficient to stabilize slopes and/or prevent sediment transport

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 19: Aerial photo taken east of the Location, facing north. Photo shows overview of the Location and fill slopes; BMPs missing or insufficient to stabilize slopes and/or prevent sediment transport

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 20: Aerial of the west end of the Location. Photo shows areas of erosion degradation. See photos 10, 11

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335844



Photo 21: Aerial photo taken from the north of the Location, facing south. Photo provides overview of the Location and storage yard.