

Inspection Photos

8/04/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335921

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 1: Photo taken from the wells on the Location. Photo shows well with incorrect Operator information.



Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335921



Photo 2: Continued from photo #1. Photo shows well with incorrect Operator information.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 3: Photo taken from the eastern production area, facing south. Photos 3-5 provides and overview of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 4: See comments under photo 3.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 5: See comments under photo 3.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 6: Photo taken from the southeast end of the Location, facing east. Photo shows areas of the Location, including fill slopes, that have not been recontoured/regraded or reclaimed to their original condition in accordance with 1003 rules. BMPs appear insufficient or missing to stabilize slopes and prevent sediment transport.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 7: Photo taken from the southeast end of the Location, facing west. See comments under photo 6.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 8: Photo of fill slopes on the southeast end of the Location. See comments under photo 6



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 9: Aerial photo taken from the south of the Location, facing north. Photo shows areas of the Location, including fill slopes, that have not been recontoured/regraded or reclaimed to their original condition in accordance with 1003 rules. BMPs appear insufficient or missing to stabilize slopes and prevent sediment transport.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 10: Photo taken from the south of the Location, facing northwest. Photo shows BMPs appear insufficient or missing to stabilize slopes and prevent sediment transport. Interim areas have not been contoured/regraded and reclaimed to their original condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 11: Photo taken from the south of the Location, facing northeast. See comments under photo 10.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 12: Photo taken from the southeastern end of the Location. Photos 12-13 provide an overview of the eastern interim areas.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 13: Photo taken from the southeastern end of the Location, facing north.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 14: Aerial photo taken from the east of the Location, facing southwest. Photo shows Interim areas have not been contoured/regraded and reclaimed to their original condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 15: Aerial photo taken from the east of the Location, facing northwest. See comments under photo 14.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 16: Photo taken from the east end of the Location, facing south. Photos 16-19 provide an overview of the location from south, southwest, northwest to north.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 17: See comments under photo 16.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 18: See comments under photo 16.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 19: See comments under photo 16. Photo also shows what appears to be a topsoil stockpile

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 20: Photo taken from the northeast end of the Location, facing south. Photo shows interim areas. Soils at the surface appear to be subsoils; it does not appear that topsoil horizons were placed back to their relative original position.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 20.b: Continued from photo 20. Photo show soil surface of interim area. it does not appear that topsoil horizons were placed back to their relative original position.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 21: Aerial photo taken from the northeast of the Location, facing southwest. Photo shows cut slopes. Interim areas have not been contoured/regraded and reclaimed to their original condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 22: Aerial photo showing cut slopes on the north end of the Location, facing northwest. BMPs appear missing or insufficient to stabilize slopes. Interim areas have not been contoured/regraded and reclaimed to their original condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 23: Aerial photo showing cut slopes on the north end of the Location, facing north. BMPs appear missing or insufficient to stabilize slopes. Interim areas have not been contoured/regraded and reclaimed to their original condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 24: Photo taken from the northeast end of the Location, facing south. Photo shows cut slopes and interim areas. Interim areas have not been contoured/regraded and reclaimed to their original condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 25: Photo taken from the northeast end of the Location, facing south. Photo shows cut slopes and interim areas. Interim areas do not appear to have been sufficiently recontoured/regraded and reclaimed to their original

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 26: Photo taken from the cut slopes on the north end of the Location, facing south. BMPs appear missing or insufficient to stabilize slopes.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 27: Photo taken from the northwest end of the Location, facing east. Photo shows northern interim areas.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 28: Photo taken from the northern interim areas, facing north. BMPs appear missing or insufficient to stabilize slopes.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 29: Aerial photo taken from the west of the Location, facing east. Photo provides overview of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 30: Aerial photo taken from the west of the Location, facing south. Photo provides overview of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 31: Photo taken from the east end of the Location, facing north. Photo provides overview of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 32: Photo taken from the east end of the Location, facing east. Photo provides overview of the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 33: Photo of the slopes on the southwest end of the Location, facing south.
Photo shows erosion net BMPs in disrepair.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 34: Photo taken from the south end of the Location. Photo shows unused equipment on the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335921



Photo 35: Photo taken from the south end of the Location. Photo shows unused equipment on the Location. Photo shows fence panels in disrepair.