

# Inspection Photos

8/04/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335512

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 1:** Photo taken from the north end of the Location, facing east. Photos 1-3 provide an overview of the Location from east, south to west. Photos also show drill cutting on the Location. Remediation project #11051 associated with cuttings management on the location was closed 10/2018; Interim reclamation of the Location has not been conducted.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 4:** Photo taken from the northwest end of the Location, facing east. Photos 4-5 provide an overview of the Location from east to south. Photos also show drill cutting on the Location. Remediation project #11051 associated with cuttings management on the location was closed 10/2018; Interim reclamation of the Location has not been conducted.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 5:** See comments under photo 4.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 6:** Photo taken from the west end of the Location, facing south. Photo shows areas where cuttings appear to have been pushed upon, and over the berm during management.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 7:** Photo taken from the west end of the Location, facing north. Photo shows areas where cuttings appear to have been pushed upon, and over the berm during management.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 8:** Photo taken from the west end of the Location, facing south. Photo shows topsoil stockpile and drill cuttings. There does not appear to be BMPs in place to segregate cuttings from the topsoil.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 9:** Continued from photo 8. Photo shows topsoil stockpile and drill cuttings. There does not appear to be BMPs in place to segregate cuttings from the topsoil.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 10:** Photo taken from the southwest end of the Location, facing north. Photo shows concrete debris. Photo also shows topsoil stockpile and drill cuttings.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 11:** Photo taken from the south end of the Location, facing west. Photo shows topsoil stockpile

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 12:** Photo taken from the east end of the Location, facing north. Photo shows drill cutting on the east end of the Location. Remediation project #11051 associated with cuttings management on the location was closed 10/2018; Interim reclamation of the Location has not been conducted.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335512



**Photo 13:** Photo of active wells on the Location.