

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/11/2020

Submitted Date:

08/11/2020

Document Number:

696302254

FIELD INSPECTION FORM
 Loc ID 431634 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10503

Name of Operator: RED HAWK PETROLEUM LLC

Address: 575 N DAIRY ASHFORD STE 201

City: HOUSTON State: TX Zip: 77079

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|----------------------|---------------------------------|
| Shepard, DeAnn | | dshepard@pedevco.com | All Inspections |
| Boyd, William | | wboyd@pedevco.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|---------------|-------------|
| 431633 | WELL | PR | 02/01/2018 | OW | 123-36703 | Buchner 2-2H | PR |
| 431634 | LOCATION | AC | 02/01/2018 | | - | Buchner 2-2H | AC |

General Comment:

Location

Overall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | WEEDS | | |
| Comment: | Weeds on location and are abundant in Reclamation Area. See photos | | |
| Corrective Action: | Comply with Rule 603.f. and 1003.f. | Date: | 09/11/2020 |
| Type | OTHER | | |
| Comment: | Stained Soil all around Pumping Unit and in Engine Housing, see photos | | |
| Corrective Action: | For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e." | Date: | 08/26/2020 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused Chemical Tank and Containment, see photos | | |
| Corrective Action: | Comply with Rule 603.f. | Date: | 09/11/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | Date: | |

| | | | |
|-------------------------------|----------------------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heater Treater | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Flare | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLs | FIBERGLASS AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|-----------------------|
| | | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 3 | 400 BBLs | STEEL AST | | 60.332000,-104.067010 |
| Comment: | | | | | |

| | | | |
|--------------------|-------------|---------------------|---------------------|
| Corrective Action: | | Date: | |
| Paint | | | |
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |
| Berms | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) |
| Metal | Adequate | Walls Sufficient | Base Sufficient |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Flaring: | | | |
| Type | Field Flare | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected FacilitiesFacility ID: 431633 Type: WELL API Number: 123-36703 Status: PR Insp. Status: PR**Producing Well**Comment: [PR](#)

Corrective Action:

Date:

Facility ID: 431634 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: [Active Producing Facility](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Wednesday 08/05/2020 at approximately 12:21, I, Inspector Erica Petrie, conducted a Field Inspection at Redhawk Petroleum LLC, Buchner 2-2H, at Location #431634 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds are abundant in the Reclamation Area and Production Area. Control weeds per Rules 603.f. and 1003.f. Corrective Action Date 09.11.2020.</p> <p>Stained Soil around the Pumping Unit. See photos Comply with Rule 907.e. Corrective Action Date 08.26.2020.</p> <p>Unused Chemical Tank and Containment in Center of location, see photos. Comply with Rule 603.f. Corrective Action Date 09.11.2020</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p> <p>COGCC Inspection Report Summary</p> | petrie | 08/11/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696302259 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221505 |