

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/13/2020

Submitted Date:

08/13/2020

Document Number:

697001810**FIELD INSPECTION FORM**Loc ID 407684 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10131Name of Operator: ST JAMES ENERGY OPERATING INCAddress: PO BOX 1210City: JACKSON State: WY Zip: 83001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		cogccinspection@pdce.com	
Jenkins, Steve		steve.jenkins@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243662	WELL	PA	05/01/1998	DA	123-11454	DRAKE 8-2	PA

General Comment:

Re-entry and replugin by PDCE.

Inspected FacilitiesFacility ID: 243662 Type: WELL API Number: 123-11454 Status: PA Insp. Status: PA**Workover**Comment: Cut/cap wellbore at 10' below grade, TOC is 4' below wellbore cap.Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697001811	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223425