

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2020

Submitted Date:

08/13/2020

Document Number:

699302345

**FIELD INSPECTION FORM**

Loc ID 331525 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                | Comment                         |
|--------------|-------|--------------------------------------|---------------------------------|
| ,            |       | Cogcc.inspections@crestone<br>pr.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 263126      | WELL | PR     | 03/01/2018  | GW         | 123-20838 | TOWNSEND 34-5 | PR          |

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | adequate |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  | Date: |  |
| Corrective Action: |  |       |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | Ag fence |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                           |                                  |       |                 |
|---------------------------|----------------------------------|-------|-----------------|
| Type: Bradenhead          | # 1                              |       | corrective date |
| Comment:                  | appears to be plumbed to surface |       |                 |
| Corrective Action:        |                                  | Date: |                 |
| Type: Ancillary equipment | # 1                              |       |                 |
| Comment:                  | automation                       |       |                 |
| Corrective Action:        |                                  | Date: |                 |
| Type: Plunger Lift        | # 1                              |       |                 |
| Comment:                  |                                  |       |                 |
| Corrective Action:        |                                  | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 263126 Type: WELL API Number: 123-20838 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p><a href="#">COGCC Inspection Report Summary</a><br/>                     On Thursday 8/13/2020 at approximately 1345 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:<br/>                     Townsend34-5 at API</p> <p># 05-123-20838 in Weld County Colorado.<br/>                     While there, I observed a wellsite.<br/>                     During this inspection no compliance issues were observed:<br/>                     See attached photos.<br/>                     Location is dry, weather is clear.<br/>                     No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.<br/>                     This is a summary of inspection report</p> | revasr | 08/13/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 699302346    | location pics | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223529">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223529</a> |