

Inspection Photos

Location Name: GUNNISON ENERGY LLC Spadafora 1190 /20-21 H1

Location ID: 417369



Photo #1715 from entrance to location



Photo #1715 from entrance to location

Inspection Photos

Location Name: GUNNISON ENERGY LLC Spadafora 1190 /20-21 H1

Location ID: 417369



Photo #1717 Multiple places with unused equipment.



Photo #1718 Multiple places with unused equipment.

Inspection Photos

Location Name: GUNNISON ENERGY LLC Spadafora 1190 /20-21 H1

Location ID: 417369



Photo #1719 stained soil.



Photo #1721 oily fluid in cellar ring.