

Inspection Photos

API: 063-06043

Operator: CITATION OIL & GAS CORP

Inspection Date: 8/11/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06043 | Date: 8/11/2020

Inspection Photos



Photo 1. This is a 2011 aerial image of the location. There are multiple areas of disturbance shown by red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06043 | Date: 8/11/2020

Inspection Photos



Photo 2. Facing east toward the location. This area of the location is being farmed around due to the prescience of a pipe riser that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06043 | Date: 8/11/2020

Inspection Photos



Photo 3. Pipe riser at the location has not been removed since previous inspection. Corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06043 | Date: 8/11/2020

Inspection Photos



Photo 4. Facing northeast toward the location. The pipe riser is interfering with farming operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06043 | Date: 8/11/2020

Inspection Photos



Photo 5. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06043 | Date: 8/11/2020