

Inspection Photos

Loc#322404

Operator: Maralex

Insp:#692402422

Insp Date: 7/31/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

July 31, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Baldy Creek Loc#322404



Photo#2:
Overview of Location to Southwest

July 31, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Baldy Creek Loc#322404



Photo#3:
View North along base of cut slope.

July 31, 2020



Photo#4:
North end of Cut slope. Noxious weed,
Houndstongue in foreground.



Photo#5:
Erosion and undermining of root systems at top of Cut.
Note undermined old fencing, indicated by arrows.

Photo#6:
Erosion and undermining of root systems at top of Cut.

July 31, 2020



Photo#7:
Noxious weeds established on site.

July 31, 2020



Photo#8:
Noxious weeds established on site.



Photo#9:
Noxious weeds established on site



Photo#10:
Noxious weeds established on site.

July 31, 2020



Photo#11:
Open riser at front of Pump Jack.



Photo#12:
Subsidence/wormhole under rocked drain area.

July 31, 2020