

Inspection Photos

Loc#322436

Operator: Maralex

Insp:#692402423

Insp Date: 7/31/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Northwest.

July 31, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Baldy Creek Federal Loc#322436



Photo#2:
View over East fill slope to North.

July 31, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Baldy Creek Federal Loc#322436



Photo#3:
View Northwest along cut slope.

July 31, 2020



Photo#4:
North end of cut slope.




Photo#5:
Erosion and undermining of root systems at top of cut.



Photo#6:
Erosion and undermining of root systems at top of cut.

July 31, 2020



Photo#7:
Noxious weeds established on site.

Photo#8:
Noxious weeds established on site.

July 31, 2020



Photo#9:
Unused equipment and Debris.

July 31, 2020



Photo#10:
Anchors not Marked.