

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/13/2020

Submitted Date:

08/14/2020

Document Number:

696201641

FIELD INSPECTION FORMLoc ID 314367 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 0

Name of Operator: _____

Address: _____

City: _____ State: _____ Zip: _____

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------|---------------------------|
| Patterson, Chris | | spwu@chevron.com | All Inspections per Olson |
| Olson, Andrew | | andrewolson@chevron.com | Principal Agent |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 228584 | WELL | IJ | 07/16/2015 | ERIW | 103-05481 | EMERALD 25 | RI |

General Comment:

On 8/13/2020, Reclamation Specialist Trujillo conducted a good housekeeping inspection at Chevron USA Inc's Emerald 25 location in Rio Blanco County, Colorado.

This inspection is a followup to inspection #696201281 to document compliance with the following corrective actions 603.f: Remove pipe debris

It was observed in this inspection that pipe debris has been removed.

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

| | | | |
|--------------------|---|-------|--|
| Type | DEBRIS | | |
| Comment: | Inspection #696201281 documented pipe debris on the south end of the Location and required Operator to comply with Rule 603.f It was observed in this inspection that debris has been removed; Corrective action has been addressed. | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 228584 Type: WELL API Number: 103-05481 Status: IJ Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------|---|
| 696201642 | Debris removed | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5224312 |