

Inspection Photos

API: 061-06899

Operator: MCCOY PETROLEUM CORPORATION

Inspection Date: 8/11/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 8/11/2020

Inspection Photos



Photo 1. Facing north toward the beginning of the access road. The access from the county road has been regraded and soils decompacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 8/11/2020

Inspection Photos



Photo 2. The soils were ripped along the access road. The cattle guard will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 8/11/2020

Inspection Photos



Photo 3. The soils were ripped but will need to be adequately tilled to establish a seed bed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 8/11/2020

Inspection Photos



Photo 4. Facing west toward the location from a distance. The location has been recontoured and pits are backfilled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 8/11/2020