

Inspection Photos

API: 121-10880

Operator: MERIT ENERGY COMPANY

Inspection Date: 8/12/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 121-10880 | Date: 8/12/2020

Inspection Photos



Photo 1. Facing northwest toward the location. There is an active well at the location listed under another operator. It does not appear that the [JONES #35-26](#) well was ever drilled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 121-10880 | Date: 8/12/2020

Inspection Photos



Photo 2. The active well at the location is the JONES #34-26 well listed under another operator. No other well or equipment was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 121-10880 | Date: 8/12/2020