

Inspection Photos
Location Name: Opal 14-34
Location ID: 318936



Photo 1 WH Flow line valves appear to be closed. Weeds around well head



Photo 2 loc pic. Weeds on location and around equipment.

Inspection Photos
Location Name: Opal 14-34
Location ID: 318936



Photo 3 Crude oil tank. Weeds in and around containment. NFPA placards missing, no tank volume, Tank needs to be painted tank visible from county road.



Photo 4 Stained soil under crude tank load out line. Mechanical issuer valve appears to be leaking. WEEDS

Inspection Photos
Location Name: Opal 14-34
Location ID: 318936



Photo 5 WEEDS and Risers not LOTO.



Photo 6 meter test.



Inspection Photos
Location Name: Opal 14-34
Location ID: 318936



Photo 7 Vertical separator and house. WEEDS



Photo 8 Vertical separator house in disrepair.

Inspection Photos
Location Name: Opal 14-34
Location ID: 318936



Photo 9 WEEDS on location and around equipment.



Photo 10 produced water tank. WEEDS and NFPA placards faded and tank volume faded.

Inspection Photos
Location Name: Opal 14-34
Location ID: 318936



Photo 11 loc pic. Weeds on location and around equipment.