

Inspection Photos
Operator: BP America
API: 067-08835
Date: 8/13/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with crested wheatgrass, intermediate wheatgrass, and western wheatgrass.



Photos 3. View of musk thistles that appear to be herbicide treated within the project area.



Photo 4. View of reference area comprised of a mosaic of sagebrush shrubland and irrigated grass field.