

Inspection Photos
Operator: BP America
API: 067-09624
Date: 8/13/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Hay identified during previous inspection is moved off of the working area south of the well pad.



Photos 3. View of the southern project area from the well pad entrance facing westward. Revegetation is progressing, largely with crested wheatgrass and western wheatgrass.



Photos 4. View of twine debris within the interim reclamation area.



Photo 5. View of reference area comprised of pinyon and juniper woodland with grasses such as western wheatgrass in the understory.