

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: Chain link barbrd wire and metal shed

Corrective Action: Date:

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment:

Corrective Action: Date:

Type: Bradenhead # 1

Comment: Appears to be plumbed to surface

Corrective Action: Date:

Venting:

Yes/No NO

Comment:

Corrective Action: Date:

Flaring:

Type

Comment:

Corrective Action: Date:

Inspected Facilities

Facility ID: 299233 Type: WELL API Number: 001-09680 Status: IJ Insp. Status: AC

BradenHead

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

Completion

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Routine inspection	finkenbc	08/19/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900302	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5228118