

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2020

Submitted Date:

08/13/2020

Document Number:

690006380

FIELD INSPECTION FORM

Loc ID 302455 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10580
Name of Operator: EXPEDITION WATER SOLUTIONS COLORADO LLC
Address: 2015 CLUBHOUSE DR SUITE 201
City: GREELEY State: CO Zip: 80634

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Sellmer, Travis		tsellmer@expedition-water.com	
Gintautas, Peter		peter.gintautas@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Goddard, Jim		jgoddard@expedition-water.com	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159270	UIC DISPOSAL	AC	04/27/2009		-	HPD PLATTEVILLE 1	SI
298847	WELL	IJ	04/12/2012	DSPW	123-29168	HPD PLATTEVILLE 1	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
Produced Water	Truck Loadout	>= 5 bbls		
Comment:	Refer to inspection document: 697601000			
Corrective Action:	Refer to inspection document: 697601000			Date: <u>07/29/2020</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Sump Surrond Chainlink		
Corrective Action:		Date:	

Equipment:

Type	Quantity	Comment	Corrective Action	Date	corrective date
Prime Mover	# 1	750 HP			
Prime Mover	# 1	500 Horsepower			
Other	# 2	Injection Pumps.			
Emission Control Device	# 1				

Comment:	
Corrective Action:	Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	1000 BBLs	STEEL AST		40.216920,-104.719690
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Concrete	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	2000 Bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	750 Bbl				
Other (Type)					

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shared with 1000 Bbl Tank						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	6	OTHER	STEEL AST		,	
Comment:						
Corrective Action:				Date:		
Paint						
Condition						
Other (Content)						
Other (Capacity)	750 Bbl					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shared with 1000 Bbl tank.						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type	Ignitor/Combustor					
Comment:						
Corrective Action:					Date:	

Comment	User	Date
<p>Thursday August 13, 2020 On-site inspection of UIC well and battery. Weather warm and skies clear.</p> <p>Commercial disposal facility with temporarily suspended commercial operations.</p> <p>There is an existing corrective action associated with spill number: 452769 The required actions and associated corrective action date remain unchanged by today's inspection. The comments from the previous inspection are repeated below for reference purposes.</p> <p>"spill 452769 was closed based on assumed actions to be undertaken in site investigation and remediation project 10805. Data has been submitted indicating soils remaining at site meet Table 910-1 thresholds. No request for closure of the site investigation and remediation project 10805 was ever received. The site has changed operators but either can submit a supplemental eForm 27 with Remediation Completion Report check box requesting closure of project. other operations at site not inspected in this report. appeared operations were shut in at time of inspection"</p> <p>Additionally, there is an ongoing effort to address the bradenhead pressure. Today's reading of 175 PSI indicates that this process has yet to be successful in addressing this issue. In conversation with the operators representative today, they have encountered delays in performing the work due to equipment and manpower constraints but believe they will be able to execute the bleeding down and flaring aspects of this project "soon". Note: completion of the existing process does not preclude further requirements by the COGCC Engineering to reduce/eliminate the bradenhead pressure.</p> <p>This concludes the summary of this inspection report.</p>	carlilec	08/13/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402465959	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223108
690006381	Battery Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223102
690006382	Wellhead Related Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223103