

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2020

Submitted Date:

08/13/2020

Document Number:

699700189

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORT WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Merlin Rasmussen		Merlin_rasmussen@xtoenergy.com	SSHE Coordinator
Dooling, Jessica	970-675-4122	jessica_dooling@xtoenergy.com	Piceance EHS Supervisor
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

On July 28, 2020, COGCC Environmental Staff (John Heil) conducted an Environmental field inspection of XTO ENERGY INC (XTO operator #100264) Yellow Creek Compressor Spill/Release ID 477401. Personnel with XTO were also onsite excavating the spill/release area at time of inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	corrective date
Compressor		
Comment: The operator is not in compliance with Rule 313.B.		
Corrective Action:	Within 14-days of receiving this Field Inspection Report, the operator shall bring this compressor station into compliance per Rule 313.B., notifying Debbie Lutz, Alex Fischer, and John Heil when the Form 12 has been submitted.	Date: <u>08/27/2020</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: _____

Flaring:

Type		
Comment:		
Corrective Action:		Date: _____

Environmental

Spill/Remediation:

Comment: [See Spill/Release ID 477401 for more information.](#)
 7/28/2020 COGCC staff observed an excavation located at the southwest corner of the YELLOW CREEK BRIDGE GAS PLANT (Facility ID 434309). Hydrovac material was stockpiled in a steel container and the excavated material was partially stockpiled on liner material. Both hydrovac and excavated material had a detectable hydrocarbon odor and some potential staining was observed. Impacted material from the spill/release was inadequately contained within the liner material.

Corrective Action: Properly store E&P waste per Rule 907.a and clean up per Rule 906.a.
 Location surface shall be sampled in areas where the impacted material was not properly stored on the liner material.

Date: 09/13/2020

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402466393	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223503
699700191	20200728 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223500