

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/12/2020

Submitted Date:

08/13/2020

Document Number:

701001116

FIELD INSPECTION FORM

Loc ID 310907 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10730
Name of Operator: CWC PETRO LLC
Address: 6957 #A ISABELL LN
City: ARVADA State: CO Zip: 80007

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Clark, Christopher	(303) 519-7870	cwclark@cwcpetro.com	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296428	WELL	IJ	02/01/2017	DSPW	125-11298	MILDRED SOUTH WDW 2-15	AC

General Comment:

Routine UIC Inspection

Location

Lease Road:			
Type	Access		
comment:	Access off of main county road		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:	Update to current operator		Date: 11/12/2020
Type	WELLHEAD		
Comment:	Lease sign by fiberglass shed		
Corrective Action:	Update to current operator		Date: 11/12/2020

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around location		
Corrective Action:			Date:

Equipment:				corrective date
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Triplex pump, electric circ pump, filter pots inside metal shed			
Corrective Action:				Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLS	FIBERGLASS AST		39.817980,-102.488590
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 296428 Type: WELL API Number: 125-11298 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>-5" Hg</u> (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg <u>0 PSIG</u>	Previous Test Pressure _____	Inj Zone: <u>LKMR</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>04/28/2015</u>
			AnnMTReq: <u>NO</u>

Comment: CASING HAD LIGHT BLOW, DIED IMMEDIATELY. TBG IJ @ -5" Hg

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: WELL IS PAST DUE FOR A 5 YEAR MIT (DUE DATE WAS 4/28/2020). No current Mechanical Integrity Test (MIT) on record or delinquent as required by Rule 326 a (4) A. Contact dnr_cogccengineering@state.co.us with resolution plan Date: 08/22/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402466492	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5223614