

# Inspection Photos

Operator: Catamount Energy  
API: 067-05427  
Date: 8/18/2020



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing with dense rubber rabbitbrush, western wheatgrass, and crested wheatgrass.



Photo 3. View of stormwater BMPs within the western project area, appear to be functioning at this time.





Photo 4. View of house tap within the northern project area.



Photo 5. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland vegetation with grasses such as James galleta, blue grama, needleandthread grass and forbs such as *Heterotheca villosa* and Townsend daisy.