

Inspection Photos  
Operator: Elm Ridge  
API: 067-05467  
Date: 8/18/2020



Photo 1. View of the project area from the northern edge facing center. Revegetation is progressing in a grazed condition with grasses not in identifiable condition and rubber rabbitbrush.





Photo 2. View of tubing that remains in the project area after domestic tap equipment is removed.





Photo 3. Another view of tubing that remains after domestic tap was removed, facing northward.





Photo 4. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland vegetation with grasses such as James galleta, blue grama, needleandthread grass and forbs such as *Heterotheca villosa* and Townsend daisy.