

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2020

Submitted Date:

08/20/2020

Document Number:

699601628

**FIELD INSPECTION FORM**

Loc ID 337748 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 38 PALMER CREST CT  
City: SPRING State: TX Zip: 77381

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288459	WELL	PR	12/14/2006	GW	125-10554	SALVADOR 14-28 5N46W	PR

**General Comment:**

[Routine Site Inspection FIR - SATISFACTORY](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track grassland		
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:
Type	BATTERY		
Comment:	GMR		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No	
Comment:	NA
<input type="checkbox"/> Multiple Spills and Releases?	

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Steel panel		
Corrective Action:			Date:

<b>Equipment:</b>		corrective date
Type: Gas Meter Run	# 1	
Comment:	Calibration Cert. in place	
Corrective Action:		Date:
Type: Other	# 0	
Comment:	No change in equipment inventoried	
Corrective Action:		Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 288459 Type: WELL API Number: 125-10554 Status: PR Insp. Status: PR

**Producing Well**

Comment: [GW](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for erosion management](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine FIR</a>	schureky	08/20/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699601642	GMR-Signage-Calibration Cert.- PJ (background)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5228732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5228732</a>