

Inspection Photos
Operator Name: STEHLE OIL COMPANY
Facility ID: 312978
ILES DOME (OWP) 3



Land owner entrance sign, Locked Gate at entrance to access road, Check in at COLOWYO guard office on HWY 13



Access road in good condition

Inspection Photos
Operator Name: STEHLE OIL COMPANY
Facility ID: 312758
ILES DOME (OWP) 3



Location photo, No fence installed, open range grazing land



Location photo with location 312758 white storage tank in background

Inspection Photos
Operator Name: STEHLE OIL COMPANY
Facility ID: 312758
ILES DOME (OWP) 3



Wellhead



**Wellhead with 55gal drum bung
installed**

Inspection Photos
Operator Name: STEHLE OIL COMPANY
Facility ID: 312758
ILES DOME (OWP) 3



Wellhead with Polished rod installed in wellhead



One riser on location, might be off location flowline to location 312758

Inspection Photos
Operator Name: STEHLE OIL COMPANY
Facility ID: 312758
ILES DOME (OWP) 3



Pump and sucker rods staged by wellhead



Photo of pump and filter screen