

# Final Reclamation Inspection

August 13, 2020

Operator: EDDY OIL COMPANY - 26420

Location ID: 322675

Inspection Document #: 697501903

Weld County, CO

NWNW Section 26 T4N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: DUPPER #2  
Location ID: 322675



**Photo 1.** Photo taken from the northern access road, facing South. Photo illustrates vegetative growth within the access road; however, it is not uniform and reflective of reference area vegetative levels.

Inspection Photos  
Location Name: DUPPER #2  
Location ID: 322675



**Photo 2.** Photo taken from another portion of the access road, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: DUPPER #2  
Location ID: 322675



**Photo 3.** Photo taken from another portion of the access road, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: DUPPER #2  
Location ID: 322675



**Photo 4.** Photo taken from western well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: DUPPER #2  
Location ID: 322675



**Photo 5.** Photo taken from western well location, facing Southwest. See comments under Photo 1.

Inspection Photos  
Location Name: DUPPER #2  
Location ID: 322675



**Photo 6.** Photo taken from western well location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: DUPPER #2  
Location ID: 322675



**Photo 7.** Reference photo taken east of the well location, facing East. See comments under Photo 1.