

Location			
Lease Road:			
Type	Access		
comment:	Weeds overgrown at location entrance		
Corrective Action:	Comply with Rule 603.f	Date:	09/03/2020
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	adaquate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Comply with Rule 907.e	Date:	09/04/2020
Type	OTHER		
Comment:	Mechanical issue leaking seals on pump jack gear box		
Corrective Action:	Comply with Rule 605.d	Date:	09/04/2020
Type	OTHER		
Comment:	Stained ground at Pump Jack base		
Corrective Action:	Comply with Rule 1002..(2).D	Date:	09/04/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated steel pipe and angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	meter box and transformer have fabricated steel pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel, transformers and meter box		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241148 Type: WELL API Number: 123-08936 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 8/20/2020 at approximately 1250 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: center;">Sidney Strear #6 at API #05-123-08936 in Weld County Colorado.</p> <p>While there, I observed a well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>907.e housekeeping: Stained soil around WH. CA date 9-4-2020, see photos 2 & 9.</p> <p>603.f housekeeping: Weeds overgrown at location entrance. CA date 9-3-2020 see photo 3.</p> <p>605.d Mechanical issue: Seals leaking on pump jack gear box. CA date 9-4-2020 see photos 6 & 8.</p> <p>1002..(2).D housekeeping: Stained ground at the base of pump jack. CA date 9-4-2020 see photos 5 & 7.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	08/20/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302410	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229180