

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2020

Submitted Date:

08/20/2020

Document Number:

699302418**FIELD INSPECTION FORM**Loc ID 336348 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------|---------------------------------|
| , | | rwatzman@kpk.com | All Inspections |
| , | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 240895 | WELL | PR | 06/04/1976 | OW | 123-08683 | SIDNEY STREAR 4 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | |
|---------------------------|------------------------|------------------|
| Good Housekeeping: | | |
| Type | OTHER | |
| Comment: | Stained soil around WH | |
| Corrective Action: | Comply with Rule 907.e | Date: 09/04/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | |
|--------------------|---|-------|
| Fencing/: | | |
| Type | OTHER | |
| Comment: | meter box and transformers have fabricated steel pipe | |
| Corrective Action: | | Date: |
| Type | WELLHEAD | |
| Comment: | barb wire | |
| Corrective Action: | | Date: |
| Type | PUMP JACK | |
| Comment: | fabricated angle iron | |
| Corrective Action: | | Date: |

| | | | |
|---------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Meter box, electric panel and transformers. | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | electric motor | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|--|
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 240895 Type: WELL API Number: 123-08683 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 8/20/2020 at approximately 1430 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Sidney Strear #4 at API #05-123-08683 in Weld County Colorado.</p> <p>While there, I observed a well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>907.e housekeeping: Stained soil around WH, CA date 9-4-2020 see photos 2 & 3. See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | revasr | 08/20/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 699302419 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229185 |