

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2020

Submitted Date:

08/20/2020

Document Number:

690102028

FIELD INSPECTION FORM

Loc ID 320319 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 6420
Name of Operator: BARNES PETROLEUM CORPORATION
Address: 4356 RICKOVER DR
City: DALLAS State: TX Zip: 75244

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203442	WELL	TA	04/23/2002	GW	001-09001	ROSENER (OWP) 1	TA

General Comment:

[COGCC OWP Inspection; Flowline Inspection](#)
[Photos Uploaded](#)

Inspected Facilities

Facility ID: 203442 Type: WELL API Number: 001-09001 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is TA; No flowline connected to wellhead. No evidence of off location tank battery found. Steel fencing/ barricade laying down around wellhead. Existing signage at lease road entrance (at 152nd Ave) and wellhead. Flowline pipe found NE of wellhead is surface trash/ debris only; No buried flowlines/ risers identified. The wellhead valve was LOTO during this field inspection.

Corrective Action: _____ Date: _____

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: _____
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
As outlined on previous FIR Doc #674102961 submitted on 03/11/2016; OGCC inspectors were on location on 3/11/16 to inspect the condition of the well. The wellhead configuration is shown in the attached photo. OGCC inspectors were able to get to the wellhead in their trucks, however, roads out to the location would not allow any pulling unit or workover rig to access the wellhead, road will need to be worked on if a rig is to get to the wellhead. OGCC inspectors observed old steel piping to the northeast of the wellhead, photo attached. Bradenhead is not at surface, inspector was unable to locate bradenhead.	maclarej	08/20/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102035	Wellhead LOTO; fencing and signage (view west)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229156
690102036	Pipe debris; view SW to wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229157
690102037	Signage at lease road access	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229158