



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbwire		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 422033 Type: WELL API Number: 123-33137 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: T/A  
 Recent Forms include the following:  
 Form 42 #402442261  
 Form 5A #402413419  
 Form 21#402443205

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
COGCC Inspection Report Summary On Monday 8/24/20 at approximately 0853hrs, I, Inspector Adam Burns, Conducted an on-site inspection at French Lake 4-63-36 #1M of Bonanza Creek Energy at Location ID: 422041 in Weld County, Colorado. While there, I observed a well that is T/A. Recent Forms include the following: Form 42 #402442261 Form 5A #402413419 Form 21#402443205 No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.	burnsa	08/24/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102291	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230578">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230578</a>