

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2020

Submitted Date:

08/24/2020

Document Number:

700300068

**FIELD INSPECTION FORM**

Loc ID 313469 Inspector Name: LABOWSKIE, STEVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LP  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Koehler, Bob		bob.koehler@state.co.us	
, General		CO2Source_Regulatory@kindermorgan.com	<a href="#">All Inspections 2-16-2018</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224135	WELL	IJ	01/31/2008	DSPW	083-06195	MCELMO DOME UNIT 26-38-18 (EPA) YWD-1	AC
450909	TANK BATTERY	AC	06/01/2017		-	Yellow Jacket YWD-1 Tank Battery	AC

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	injection building		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Note: live stock carcas (calf) on edge of pad		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Open top dumpster, not bear proof with mix of trash including food generated waste and what appeared to be used injection filters		
Corrective Action:	Comply with Rule 1204.a(1) (note: better container will help with loose trash) Also ensure proper disposal of E&P waste (filters)	Date:	09/01/2020
Type	TRASH		
Comment:	small trash along west edge of pad		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	fiberglass sructures around wellhead and injection/water filtering equipment		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	fiberglass storage building with injection equipment		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	wellhead		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	chemical injection system		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	deadmen on west/downgradient side are somewhat overrun with gravel and vegetation		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 224135 Type: WELL API Number: 083-06195 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: LDVLL

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 08/08/2005

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: GRAVITY FEED

Test Type: \_\_\_\_\_ Tbg psi: vac Csg psi: 1 BH psi: 0

Insp. Status: Pass

Comment: Injecting under gravity feed during test. Annulus full w/ packer fluid, 1 psig upon arrival. Pressure to 395 psig, 394.2 at 10 min, 394.1 at 15 min, no increase in BH or tubing pressure during test.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 450909 Type: TANK API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	truck loading station
				Material Handling And Spill Prevention	Pass	spill prevention on chemical system
Compaction	Pass					

Comment: [some erosion on west side/downgradient side of graveled pad area could use some BMPs](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300071	not bear proof trash recepticle	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230623">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230623</a>
700300072	trash, erosion ,carcass	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230624">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230624</a>
700300073	trash erosion	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230625">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230625</a>
700300074	tanks	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230626">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230626</a>