

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2020

Submitted Date:

08/24/2020

Document Number:

699501648**FIELD INSPECTION FORM**Loc ID 319977 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Burn, Diana		diana.burn@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202080	WELL	SI	02/01/2020	OW	001-07485	BREDEHOFT 1	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 1

Comment: Corrective Action: Date: 

Type: Ancillary equipment

# 1

Comment: Automation

Corrective Action: Date: 

Type: Emission Control Device

# 1

Comment: Corrective Action: Date: 

Type: Bradenhead

# 1

Comment: Corrective Action: Date: 

Type: Prime Mover

# 1

Comment: Gas Motor

Corrective Action: Date: 

Type: Pump Jack

# 1

Comment: Corrective Action: Date: 

Type: Deadman # &amp; Marked

# 4

Comment: Corrective Action: Date: 

Type: Bird Protectors

# 2

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Some erosion of berm was noticed at time of inspection.			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		,
Comment:	80 BBL				
Corrective Action:			Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:			Date:	

Venting:

Yes/No	YES		
Comment:	At time of inspection location appears to be flaring gas natural gas that is produced from well, see pic 1		
Corrective Action:	Contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.	Date:	08/24/2020

Flaring:

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 202080 Type: WELL API Number: 001-07485 Status: SI Insp. Status: SI

**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 8/24/2020 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Bredehoft 1</p> <p>Company Name- KPK</p> <p>API- 05-001-07485</p> <p>In Adams County Colorado.</p> <p>While there, I observed producing well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>At time of inspection location appears to be flaring gas natural gas that is produced from well, see pic 1</p> <p>Contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details. 8/24/2020</p> <p>COGCC production data shows that gas has not been recorded from wellsite since 2/1/2008.</p> <p>At time of inspection ECD appeared to be flaring natural gas produced from Bredehoft 1 well.</p> <p>Corrective actions from previous inspection Document # 693501437 appear to have been addressed. Some weeds remain around inside deadmen area however appear to have been addressed since last inspection.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	08/24/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501649	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230803">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230803</a>