

**Inspection Photos**  
**Operator: Hilcorp Operating**  
**API: 067-08111**  
**Date: 8/20/2020**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of erosional channel approximately 1 foot wide and deep, eroding the western project area.



Photo 3. View of the western project area from the southwestern corner facing northward. Revegetation is progressing in portions with crested wheatgrass and western wheatgrass. Sparse revegetation remains in the recent remediation area within the western project area.



Photo 4. View of remediation area in the northwestern project area. Little desirable vegetation is becoming established here. Revegetation needs to be monitored and re-seeded if desirable vegetation is not becoming established.



Photo 5. View of dense kochia up to 6-feet tall within the southeastern project area.



Photo 6. View of dense kochia growing along and within the access road, facing southward.



Photo 7. View of reference area comprised of irrigated grass field with grasses such as smooth brome, foxtail barley, and wheatgrasses.