

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2020

Submitted Date:

08/25/2020

Document Number:

700300070**FIELD INSPECTION FORM**Loc ID 326380 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87415**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216340	WELL	PR	07/08/2020	GW	067-07946	BONDAD 33-10 26	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	midstream riser with plate flange and barricade		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	Glycol appears black at level indicator with milky hydrate at top, see photos		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 216340 Type: WELL API Number: 067-07946 Status: PR Insp. Status: PR**Complaint**

Comment: Inspection in response to complaint doc# 200449094 for noise and odors.

Intial sound survey taken 7/23/20 at 100' and sound level for ~20 min min to kin average = 49 db(a) at 350'

Follow up sjurvey after operator made some modification and maintenence = 46 db(a) at 350' with calm winds

Odors from dehydrator noticable on site, winds were calm at time of inspection and odros were not leaving site.

Corrective Action:

Date:

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
-------------------	-------	-----------------	-------

Equipment
Separation Equipment
Wellhead(s)
Flowline
Other

Comment: No FLIR detectable leaks observed with camera in high sensitivity modeCorrective
Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300075	dehy glycol on 7-23-20	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231396
700300076	dehy glycol on 8-20-20	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231397
700300077	sound meter at 100' from compressor 4' off ground	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231398
700300078	7-23-20 noise at 100'	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231399
700300079	8-20-20 noise at 100'	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231400