

Reclamation Inspection

August 21, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 287848

Inspection Document #: 697501920

Weld County, CO

NWNW Section 18 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 1. Photo taken from the gated entrance, facing South. Photo illustrates the Operator sign has been updated and entry is now secured.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 2. Photo taken from the gated entrance, facing South. Photo illustrates stormwater controls have been installed to manage stormwater that flows onto and off the location.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 3. Photo taken from the gated entrance, facing South. Photo illustrates stormwater controls have been installed to manage stormwater that flows onto and off the location.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 4. Photo taken from the northeastern location, facing South. Photo illustrates stormwater controls have been installed to manage stormwater that flows onto and off the location.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 5. Photo taken from the northeastern location, facing West. Photo illustrates trash and debris has been removed.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 6. Photo taken from the northwestern location, facing East. Photo illustrates a stockpile of fill material used for interim reclamation locations.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 7. Photo taken from the northwestern location, facing Northwest. Photo illustrates a section of fence has been repaired.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 8. Photo taken from the western location, facing Southwest. Photo illustrates gate has been closed and secured.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 9. Photo taken from the northeastern detention pond located along the western boundary of the facility, facing North. Photo illustrates the noxious weed, Leafy spurge, has been controlled with herbicides.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 10. Photo taken from the central facility, facing Northeast. Photo illustrates the noxious weeds, Musk and Scotch thistle, have been controlled with herbicides.