

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2020

Submitted Date:

08/25/2020

Document Number:

690102030**FIELD INSPECTION FORM**Loc ID 376893 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 83154Name of Operator: STRATA PRODUCTION OPERATORSAddress: 5006 AUGUSTACity: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202960	WELL	PA	06/14/1989	OW	001-08365	POTTY BROWN 1	PA

**General Comment:**COGCC OWP Inspection; Flowline Inspection  
Photos Uploaded

**Inspected Facilities**

Facility ID: 202960 Type: WELL API Number: 001-08365 Status: PA Insp. Status: PA

**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well is PA (June 1989)  
 No flowline risers found; No gas gathering pipeline risers found in the vicinity of location.  
  
 Note: The previous field inspection Doc#673504541 performed on 06/21/2017 noted (3) pipe risers observed on location. These risers appear to have been removed. The area where the risers were located has been fenced; Reclamation/ revegetation of the ground disturbance appears to be in progress. Tank berms (subsided/ grass covered) were also observed west of/ adjacent to the fenced area.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
690102049	View west from prospect road to location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231815">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231815</a>
690102050	Tank berms west of fenced area	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231816">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231816</a>
690102051	View inside fenced area; no flowline risers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231817">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231817</a>