



40.11068, -108.19064, 5955.6ft, 294°
08/25/2020 12:12:59 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403078



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403078



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Emission control devices.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403078



40.11068, -108.19064, 5955.6ft, 296°
08/25/2020 12:15:00 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator & meter building.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403078



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Propane tank.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403078



40.11068, -108.19064, 5955.6ft, 47°
08/25/2020 12:14:02 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tanks.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403078





40.11068; -108.19064, 5955.6ft, 302°
08/25/2020 12:17:37 PM



40.11068, -108.19064, 5955.6ft, 312°
08/25/2020 12:13:18 PM



40.11068, -108.19064, 5955.6ft, 36°
08/25/2020 12:13:44 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 10. Thistle on location.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403078



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 11. Thistle on road side.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403078