

Inspection Photos
Operator: BP America
API: 067-08394
Date: 8/25/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of exposed and eroding soils on the northern cut-slope.




Photo 3. View of erosional rilling and sediment deposition at the toe of the northern cut-slope.



Photo 4. View of the southern fill slope, facing eastward. Revegetation is progressing with western wheatgrass and yellow sweetclover.



Photo 5. View of reference area comprised of ponderosa pine woodland with understory of gambel oak, Sandberg bluegrass, and forbs such as purple aster.